

<b>Date:</b> 01/16/2023	<b>Make/Model:</b> Piper PA-28-140	<b>Tail #:</b> N33560	<b>Serial #:</b> 28-7525207
<b>Airframe Hours:</b> TACH: 2125.87 TTAF: 6192.87			
<b>Misc:</b>			
<b>Engine:</b> Lycoming O-320-E3D	<b>Serial #:</b> L-40812-27A	<b>Hours:</b> SMOH: 114.49	
<b>Propeller:</b> Sensenich 74D (M74D) Series	<b>Serial #:</b> A40421	<b>Hours:</b> TTSN: 6192.87	

Piper PA-28-140

AD# Category	Eff Date	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
62-19-03 Airframe	08/28/62	Propeller Attachment Bolts	01/16/2023 TTAF: 6192.87	SB 209 DNA		No action required	Joel Newton 4389274 A & P
64-06-06 Airframe	04/06/64	Control Wheel Assembly	01/16/2023 TTAF: 6192.87	SB 396 each 100 hr inspection Dye- Pen 5X mag glass.	Yes	TTAF: 6292.87	Joel Newton 4389274 A & P
65-06-06 Airframe	03/12/65	Fuel Quantity Gauge Sender	01/16/2023 TTAF: 6192.87	SB 223 DNA	Yes*	No action required	Joel Newton 4389274 A & P
67-12-06 Airframe	07/31/67	Tube Corrosion	01/16/2023 TTAF: 6192.87	SB 240 DNA by serial number		No action required	Joel Newton 4389274 A & P
67-20-04 Airframe	09/27/67	Main Landing Gear Link	01/16/2023 TTAF: 6192.87	SB 248 DNA		No action required	Joel Newton 4389274 A & P
67-26-02 Airframe	05/22/68	Fuel Selector Valve	01/16/2023 TTAF: 6192.87	SB 249 A DNA by model		No action required	Joel Newton 4389274 A & P
67-26-03 Airframe	04/12/68	Fuel System Screens and Filters	01/16/2023 TTAF: 6192.87	SB 251 B DNA by serial number	Yes	No action required	Joel Newton 4389274 A & P
69-22-02 Airframe	07/30/79	Failure of Control Wheel	01/16/2023 TTAF: 6192.87	SL 527 D found P/N 79276-00 yokes installed both sides solid aluminum inspected ok no discrepancies noted	Yes*	No further action required	Joel Newton 4389274 A & P
70-16-05 Airframe	05/19/72	Exhaust Muffler Cracks	01/16/2023 TTAF: 6192.87	DNA by serial number	Yes*	No action required	Joel Newton 4389274 A & P
70-18-05 Airframe	09/07/70	Landing Gear Link Bolts	01/16/2023 TTAF: 6192.87	SB 248 DNA by serial number		No action required	Joel Newton 4389274 A & P
70-26-04 Airframe	06/24/71	Stabilizer Balance Weight Tube	01/16/2023 TTAF: 6192.87	SB 327 SL 576 DNA by serial number	Yes	No action required	Joel Newton 4389274 A & P
71-14-06 Airframe	07/09/71	Inadvertent Grounding of Magnetos	01/16/2023 TTAF: 6192.87	SB 313 DNA by serial number		No action required	Joel Newton 4389274 A & P
71-21-08 Airframe	10/13/71	Fuel Selector Handle	01/16/2023 TTAF: 6192.87	SB 588 DNA by serial number		No action required	Joel Newton 4389274 A & P
72-08-06 Airframe	04/14/72	Landing Gear Torque Links		SL 600 1199	Yes		Joel Newton 4389274 A & P

72-14-07 07/07/72 Airframe	Stabilator Hinge Attachment Fittings	01/16/2023 TTAF: 6192.87	SL 614 DNA by serial number		No action required	Joel Newton 4389274 A & P
72-24-02 11/17/72 Airframe	Throttle Movement Placard	01/16/2023 TTAF: 6192.87	DNA by part number		No action required	Joel Newton 4389274 A & P
74-06-02 03/18/74 Airframe	AVCON Mufflers	01/16/2023 TTAF: 6192.87	STC not installed DNA	Yes*	No action required	Joel Newton 4389274 A & P
74-09-04 04/24/74 Airframe	Rear Seat Belt Installation	01/16/2023 TTAF: 6192.87	SB 393 DNA by serial number		No action required	Joel Newton 4389274 A & P
74-13-04 06/21/74 Airframe	Throttle Control Cable	01/16/2023 TTAF: 6192.87	SL 670 DNA by serial number		No action required	Joel Newton 4389274 A & P
75-02-03 11/26/74 Airframe	Nose Wheel Fork Assembly	01/16/2023 TTAF: 6192.87	DNA by part number		No action required	Joel Newton 4389274 A & P
75-08-03 04/04/75 Airframe	Fuel Drain Valves	01/16/2023 TTAF: 6192.87	SB 450 DNA by serial number		No action required	Joel Newton 4389274 A & P
77-01-01 01/07/77 Airframe	Erroneous Fuel Quantity Gauge	01/16/2023 TTAF: 6192.87	SB 533 DNA by serial number PCW		No action required	Joel Newton 4389274 A & P
77-23-03 11/14/77 Airframe	Engine Control Rod End Bearings	01/16/2023 TTAF: 6192.87	#2 style rod end installed DNA		No action required	Joel Newton 4389274 A & P
87-08-08 R3 05/22/89 Airframe	Rescission of 87-08-08 and Subsequent Revisions		SB 886 "NORMAL USE"			Joel Newton 4389274 A & P
96-10-01 R1 12/14/98 Airframe	Landing Light	03/01/1998 TTAF: 5478.0	SB 975 replaced bracket and seal		No action required	Joel Newton 4389274 A & P
96-10-03 06/14/96 Airframe	Flap Handle Bolt	03/01/1998 TACH: 1385.0	SB 965 PCW TACH: 1385.0 3/1/98		No further action required	Joel Newton 4389274 A & P
99-05-09 03/19/99 Airframe	Induction Air Filter	01/16/2023 TTAF: 6192.87	SB 1022 K & N filter installed		No further action required	Joel Newton 4389274 A & P
10-15-10 08/31/10 Airframe	Control Wheel Shafts	01/16/2023 TTAF: 6192.87	MSB 1197 C inspection of control yoke shaft and "U" joint		No further action required	Joel Newton 4389274 A & P
13-02-13 03/11/13 Airframe	Stabilator Control System	01/16/2023 TTAF: 6192.87	MSB1245 A 10 X mag glass cleaned turn buckles inspected cables	Yes	01/2030 or TTAF: 8192.87	Joel Newton 4389274 A & P
17-14-04 08/15/17 Airframe	Oil Cooler Hose Assemblies	01/16/2023 TTAF: 6192.87	100 hrs per AD (G) fig 1 & 2	Yes*	TTAF: 6292.87	Joel Newton 4389274 A & P
18-07-03 04/20/18 Airframe	Fuel Tank Selector Cover Placards	01/16/2023 TTAF: 6192.87	SD 1309A fuel selector marking		Preflight Preflight Preflight	Joel Newton 4389274 A & P
20-24-05 12/28/20 Airframe	Main Wing Spar Corrosion	01/16/2023 TTAF: 6192.87	SB 1304 B inspection covers installed, inspection no discrepancies noted next 7 yrs	Yes	01/2030	Joel Newton 4389274 A & P



**Engine: Lycoming O-320-E3D**

AD# Eff Date Category	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
55-02-02 02/28/55 Engine	Accessory Drive Adapter Gasket	01/16/2023 TTAF: 6192.87	SB 176 DNA by serial number		No action required	Joel Newton 4389274 A & P
59-10-07 07/01/59 Engine	Cylinder Baffle Clamps	05/27/2009 TACH: 2011.4 SMOH:0.0	SB 254A PCW at overhaul		No further action required	Joel Newton 4389274 A & P
63-23-02 12/09/63 Engine	Exhaust Valves and Valve Guides	01/16/2023 TTAF: 6192.87	SB 293B DNA by part number	Yes	No further action required	Joel Newton 4389274 A & P
64-16-05 07/10/64 Engine	Oil Seal Failure in AC Fuel Pumps	05/27/2009 TACH: 2011.4 SMOH:0.0	SB 298 DNA new pump installed at overhaul		No further action required	Joel Newton 4389274 A & P
66-20-04 08/27/66 Engine	Oil Filter Adapter Gasket	05/27/2009 TACH: 2011.4 SMOH:0.0	SB307 Complied with at overhaul		No further action required	Joel Newton 4389274 A & P
73-23-01 01/13/77 Engine	Piston Pin Cracks From Grinding	01/16/2023 TTAF: 6192.87	SB 367F DNA by serial number		No action required	Joel Newton 4389274 A & P
75-08-09 08/18/77 Engine	Oil Pump Drive Shaft and Impeller	05/27/2009 TACH: 2011.4 SMOH:0.0	SB 385 C PCW at overhaul		No further action required	Joel Newton 4389274 A & P
87-10-06 R1 09/01/89 Engine	Rocker Arm Assembly	01/16/2023 TTAF: 6192.87	SB 477A DNA by serial number		No action required	Joel Newton 4389274 A & P
90-04-06 R1 05/28/91 Engine	Propeller Governor External Oil Line	01/16/2023 TTAF: 6192.87	DNA fix pitch propeller installed		No action required	Joel Newton 4389274 A & P
92-12-05 07/10/92 Engine	Piston Pin Failure	05/27/2009 TACH: 2011.4 SMOH:0.0	SB 501 B Accomplished at overhaul		No action required	Joel Newton 4389274 A & P
93-11-11 06/21/93 Engine	Diaphragm Fuel Pumps Overhauled (by AAI)	05/27/2009 TACH: 2011.4 SMOH:0.0	MSB 001 & 002 new pump installed at overhaul		No further action required	Joel Newton 4389274 A & P
95-26-02 01/24/96 Engine	Detonation Due To Low Octane	01/16/2023 TTAF: 6192.87	SI 1191 & SB 398 DNA by STC not installed		No action required	Joel Newton 4389274 A & P
96-09-10 07/15/96 Engine	Oil Pump Impeller Failure	05/27/2009 TACH: 2011.4 SMOH:0.0	SB 456F oil pump addressed at overhaul		No action required	Joel Newton 4389274 A & P
97-15-11 08/12/97 Engine	Piston Pin Failure	01/16/2023 TTAF: 6192.87	SB 527 C DNA by serial number		No action required	Joel Newton 4389274 A & P
98-02-08 03/30/98 Engine	Crankshaft Corrosion Pits	01/16/2023 TTAF: 6192.87	MSB505A 150 hp DNA	Yes	No action required	Joel Newton 4389274 A & P
98-17-11 10/19/98 Engine	Crankshafts Installed by Nelson Balancing Service	01/16/2023 TTAF: 6192.87	DNA SERVICE NOT USED		No action required	Joel Newton 4389274 A & P
04-10-14 06/25/04 Engine	Crankshaft Gear Retaining Bolt	05/27/2009 TACH: 2011.4 SMOH:0.0	MSB475 C new bolt and lock installed at overhaul	Yes	no action required unless sudden stoppage or prop strike	Joel Newton 4389274 A & P

06-12-07 07/11/06 Engine	ECI Cylinder Assemblies	01/16/2023 TTAF: 6192.87	DNA engine overhauled 2009 PCW		No action required	Joel Newton 4389274 A & P
07-04-19 R1 05/07/07 Engine	Superior Air Parts Cylinder Assemblies	01/16/2023 TTAF: 6192.87	Superior cylinder assemblies not installed		No action required	Joel Newton 4389274 A & P
09-26-12 02/04/10 Engine	ECI Cracked Cylinder Assemblies	01/16/2023 TTAF: 6192.87	ECI cylinders not installed	Yes	No action required	Joel Newton 4389274 A & P
17-16-11 08/15/17 Engine	Connecting Rod Failure	01/16/2023 TTAF: 6192.87	SD 632B Engine not listed in table 1		No further action required	Joel Newton 4389274 A & P

**Propeller: Sensenich 74D (M74D) Series**

AD# Category	Eff Date	Subject	Date/Hours at Compliance	Method of Compliance	Rec	Date/Hours Next Due	Signature and Number
60-11-08 Propeller	05/28/60	Hub Cracks	01/16/2023 TTAF: 6192.87	SB R-8-1 A prefix in serial number DNA	Yes	No action required	Joel Newton 4389274 A & P
66-23-02 Propeller	10/01/66	Corrosion Pits Under Water Soluble Mid Blade Decals	01/16/2023 TTAF: 6192.87	SB R-11 PCW		No action required	Joel Newton 4389274 A & P
03-13-17 Propeller	07/18/03	T and W Serviced Propellers	01/16/2023 TTAF: 6192.87	DNA service not used		No further action required	Joel Newton 4389274 A & P
05-14-11 Propeller	08/17/05	Southern California Propeller Serviced Propellers	01/16/2023 TTAF: 6192.87	DNA service not used		No action required	Joel Newton 4389274 A & P